



PARTS LIST

ITEM	QTY	PART NUMBER	DESCRIPTION
1	2	R012110	Battery Clamp
2	1	R012200	Battery Cover
3	1	R012310	JVT1220 battery complete with terminal hardware
4	4		M8 x 30 hex screw
5	4		8mm plain washer
6	6		8mm spring washer
7	4		M8 hex nut
8	1	R012120	Battery Strap
9	1	R012100	Battery Bracket
10	2		M8 x 20 hex bolt
11	1	PN0006G	Battery harness(Fuwa)
12	1	51-0210	Rubber Pad
13	1	BCAP14	Battery Charger
14	1	PN0005E	Charge harness

Refer Drilling template for item 9.

	Designed by Ivan	Checked by	Approved by - date	Material	Date 12/08/2014	Sheet 1 / 1
	Razor International Pty Ltd				Fuwa Power kit	
Drawing Number BKRW14					Edition	

